



Treatment for MCW Pump Impeller

Client

Waste Water Treatment Plant

Application date

July 2021.

Scope of work

Repair and coat damaged areas of main colling water pump impeller which experienced erosion corrosion as a result of everyday use.

Products

Corroglass 600 Series: A two pack cold cured vinyl ester glass flake.

Substrate

Steel.

Coating System

- Grit blasted to ISO 8501-1 Sa 2½
- Corroglass 600 series hand applied, with relative humidity <85% and steel temperature 30°C or greater than moisture dew point, to achieve a minimum of 1500 microns DFT.

For corrosion protection, thickness is normally 750 microns DFT average. For areas with increased wear, thickness increased to 1500 microns.

Coating credentials

Corroglass 600 series was selected due to its excellent performance properties in immersed environments. Due to the glassflake components in the coating, it also has superb resistance to solvents, acids and de-mineralised water and great flexibility undercutting resistance which is ideal for this particular impeller as it operates in environments amongst cool, clean water.